



New York Ave RC Lead in Water Test Results

FY21 Filter Test

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 006131	3/10/2021	3/10/2022	Ground Floor	Cooler	In hallway adjacent to janitor closet	WF-03102021-006131	5/6/2021	FT-FY21-042021-006131-A	<1	FT-FY21-042021-006131-B	<1

Food Prep Sink

Less than 5ppb - Devices requiring no remediation											
Record ID	Filter Installed Date	Filter Expiration Date	Floor	Device Type	Device Location	Water Filter's Name	Date Analyzed	1st Draw - Sample ID	FT Final Result - 1st Draw (ppb)	2nd Draw - Sample ID	FT Final Result - 2nd Draw (ppb)
WS- 006132	3/18/2021	3/18/2022	Ground Floor	Food Prep Sink	In kitchen adjacent to men's restroom	WF-03182021-006132	5/6/2021	FT-FY21-042021-006132-A	<1	FT-FY21-042021-006132-B	<1